

## BaySaver<sup>®</sup> Separator Units - List Prices

1/2K BaySaver <sup>®</sup> Separator Unit	1/2K BaySaver <sup>®</sup> Price (less shipping)\$4,060
Materials included with purchase: (2) Fernco couplers, HDPE connection pipes, a 24" HDPE reducer/adapter and (2) Marmac wraps	Estimated cost w/ manholes \$6,620

In addition to the BaySaver<sup>®</sup> ½K Unit, (2) 48" standard precast manholes with 6' sumps and (2) manhole frames with covers will be required to complete the system. The estimated cost\* of these components is \$2,560 (See above estimated cost w/manholes). Installation estimate has not been included. **BaySaver, Inc. does not supply the manholes\*\***.

1K BaySaver <sup>®</sup> Separator Unit	1K BaySaver <sup>®</sup> Price (less shipping) \$5,460
Materials included with purchase: (2) Fernco couplers, HDPE connection pipes, a 24" HDPE reducer/adapter and (2) Marmac wraps	Estimated cost w/ manholes \$8,420

In addition to the BaySaver<sup>®</sup> 1K Unit, (2) 48" standard precast manholes with 8' sumps and (2) manhole frames with covers will be required to complete the system. The estimated cost\* of these components is \$2,960 (See above estimated cost w/manholes). Installation estimate has not been included. **BaySaver, Inc. does not supply the manholes\*\***.

3K BaySaver <sup>®</sup> Separator Unit	3K BaySaver <sup>®</sup> Price (less shipping)\$8,860
Materials included with purchase: (2) Fernco couplers, HDPE connection pipes, a 36" HDPE reducer/adapter and (2) Marmac wraps	Estimated cost w/ manholes \$14,220

In addition to the BaySaver<sup>®</sup> 3K Unit, (2) 60" standard precast manholes with 8' sumps and (2) manhole frames with covers will be required to complete the system. The estimated cost\* of these components is \$5,360 (See above estimated cost w/manholes). Installation estimate has not been included. **BaySaver, Inc. does not supply the manholes\*\***.

5K BaySaver <sup>®</sup> Separator Unit	5K BaySaver <sup>®</sup> Price (less shipping) \$12,160
Materials included with purchase: (2) Fernco couplers, HDPE connection pipes, a 48" HDPE reducer/adapter and (2) Marmac wraps	Estimated cost w/ manholes \$19,320

In addition to the BaySaver<sup>®</sup> 5K Unit, (2) 72" standard precast manholes with 8' sumps and (2) manhole frames with covers will be required to complete the system. The estimated cost\* of these components is \$7,170 (See above estimated cost w/manholes). Installation estimate has not been included. **BaySaver, Inc. does not supply the manholes\*\***.

10K BaySaver <sup>®</sup> Separator Unit	10K BaySaver <sup>®</sup> Price (less shipping)\$19,060
Materials included with purchase: (2) Fernco couplers, HDPE connection pipes, a 60" HDPE reducer/adapter and (2) Marmac wraps	Estimated cost w/ manholes \$33,060

In addition to the BaySaver<sup>®</sup> 10K Unit, (2) 120" standard precast manholes with 8' sumps and (2) manhole frames with covers will be required to complete the system. The estimated cost\* of these components is \$14,000 (See above estimated cost w/manholes). Installation estimate has not been included. **BaySaver, Inc. does not supply the manholes\*\***.

XK BaySaver <sup>®</sup> Separator Unit	Call 1-800-229-7283
Custom unit for flows above 100 cfs peak design and 22 cfs treatment flow.	Call 1-600-227-7285

\*Cost varies depending on depth, site characteristics, and local costs.

\*\*The precast structures and frames/covers are purchased from a supplier of purchaser's choice. Manhole prices are estimated at F.O.B. job site.

Prices are effective September 12, 2003 and are subject to change without notice. BaySaver<sup>®</sup> prices are in US Dollars and are F.O.B. Mount Airy, MD. Customer is responsible for all applicable taxes.