

Type	JOB TASK	POTENTIAL RISK WHICH CAN BE CONTROLLED BY PPE	EYE	HAND	FOOT	BODY	OTHER REQUIREMENTS	RESP	HEAD	FALL PROTECTION	EAR	FACE	SPECIFIC PPE REQUIRED
CHP	Valve Re-Packing	Flying Objects or Physical Contamination	ANSI Z87 Approved Safety Glasses	Rubber Gloves	Ankle Supporting Shoe/Boot that meets ASTM F2413-17 M or F/I/75/C/75/PR	Long pants	Follow UVM's Lockout Tagout Program for de-energizing the system.		Hardhats as Needed.				
CHP	Boiler / Polisher Internals Removal	Flying Objects or Dusts, Physical Contamination	ANSI Z87 Approved Safety Glasses	Rubber Gloves	Ankle Supporting Shoe/Boot that meets ASTM F2413-17 M or F/I/75/C/75/PR	Elbow & Knee Pads, Long Pants or Coveralls	Follow UVM's Confined Space Program.		Hardhats as Needed.				
CHP	Boiler - Power Washing	Flying Objects	ANSI Z87 Approved Safety Glasses	Rubber Gloves	Ankle Supporting Shoe/Boot that meets ASTM F2413-17 M or F/I/75/C/75/PR	Rain Suit	Follow UVM's Confined Space Program.		Hardhats as Needed.				
CHP	Fire Box Sweeping	Flying Objects or Dusts, Heavy Metal Contamination	Full Face Respirator	Rubber Gloves	Ankle Supporting Shoe/Boot that meets ASTM F2413-17 M or F/I/75/C/75/PR	Coveralls	Follow UVM's Confined Space Program.	Full Face w/ P100 Filters	Hardhats as Needed.				
CHP	Soot Hopper Vacuuming	Flying Objects or Dusts, Heavy Metal Contamination	Full Face Respirator	Rubber Gloves	Ankle Supporting Shoe/Boot that meets ASTM F2413-17 M or F/I/75/C/75/PR	Coveralls		Full Face w/ P100 Filters	Hardhats as Needed.				
CHP	Pump Repair	Flying Objects or Dusts, Heavy Objects, and Cuts	ANSI Z87 Approved Safety Glasses	Mechanix Style or Leather Work Gloves	Ankle Supporting Shoe/Boot that meets ASTM F2413-17 M or F/I/75/C/75/PR	Long pants	Use mechanical hoist when moving/positioning pumps.		Hardhats as Needed.				
CHP	Air Tools	Flying Objects and Sound Levels	ANSI Z87 Approved Safety Glasses	Mechanix Style or Leather Work Gloves	Ankle Supporting Shoe/Boot that meets ASTM F2413-17 M or F/I/75/C/75/PR	Long pants			Hardhats as Needed.		Hearing Protection either Plugs or Muffs		
CHP	Hand Tools (General) - Saw, Wrenches, Hammers, etc.	Flying Objects, Sound Levels	ANSI Z87 Approved Safety Glasses	Mechanix Style or Leather Work Gloves	Ankle Supporting Shoe/Boot that meets ASTM F2413-17 M or F/I/75/C/75/PR	Long pants			Hardhats as Needed.				
CHP	Power Tools (General) - Saws, Drills, etc.	Flying Objects, Sound Levels	ANSI Z87 Approved Safety Glasses	Mechanix Style or Leather Work Gloves	Ankle Supporting Shoe/Boot that meets ASTM F2413-17 M or F/I/75/C/75/PR	Long pants			Hardhats as Needed.		Hearing Protection either Plugs or Muffs		

CHP	Wire Wheel Work	Flying Objects and Small Particles, Sound Levels, and Cuts	ANSI Z87 Approved Safety Glasses	Mechanix Style or Leather Work Gloves	Ankle Supporting Shoe/Boot that meets ASTM F2413-17 M or F/I/75/C/75/PR	Long pants			Hardhats as Needed.		Hearing Protection either Plugs or Muffs	Faceshield	
CHP	Cut off Wheel Work	Flying Objects and Small Particles, Sound Levels, and Cuts	ANSI Z87 Approved Safety Glasses	Mechanix Style or Leather Work Gloves	Ankle Supporting Shoe/Boot that meets ASTM F2413-17 M or F/I/75/C/75/PR	Cotton Coveralls	Follow UVM's Hot Work Permit Program for all spark generating activities.		Hardhats as Needed.		Hearing Protection either Plugs or Muffs	Faceshield	