



# Calibration complies with ISO 9001 ISO/IEC 17025 AND ANSI/NCSL Z540-1



Calibration Certificate No. 1750.01 Cert. No.: 4481-1920126

# Traceable® Certificate of Calibration for IR Therm with Wristband

#### Instrument Identification:

Model: 36934-176

S/N: 80402664

Manufacturer: Control Company

# Standards/Equipment:

Description	Serial Number	Due Date	NIST Traceable Reference		
Calibrator 50-500°C	A52364	5/19/09	1000244069		
RTD Thermometer	230252570	10/16/08	1000233104		
Digital Thermometer	20267165/21030926	9/06/08	4000-1695333		
nperature Calibration Bath TC179	A45240				
Thermistor Module	A27129	7/17/08	1000228256		
Temperature Probe	128	10/18/08	A7919076-1		

#### Certificate Information:

Technician: 104

Tem

Procedure: CAL-04

Cal Date: 7/07/08

Cal Due: 7/07/10

Test Conditions:

23.5°C

48.0 %RH 1017 mBar

Calibration Data: (New Instrument)

Cambration Data. (New Instrument)											
Unit(s)	Nominal	As Found	In Tol	Nominal	As Left	In Tol	Min	Max	±uc	TUR	
°C		N.A.		24.999	25.4	Y	23.5	26.5	0.250	>4:1	
°C		N.A.		50.06	49.8	Y	48.1	52.1	0.28	>4:1	
°C		N.A.		150.24	148.6	Y	146.2	154.2	0.39	>4:1	

# This Instrument was calibrated using Instruments Traceable to National Institute of Standards and Technology.

A Test Uncertainty Ratio of at least 4:1 is maintained unless otherwise stated and is calculated using the expanded measurement uncertainty. Uncertainty evaluation includes the instrument under test and is calculated in accordance with the ISO "Guide to the Expression of Uncertainty in Measurement" (GUM). The uncertainty represents an expanded uncertainty using a coverage factor k=2 to approximate a 95% confidence level. In tolerance conditions are based on test results falling within specified limits with no reduction by the uncertainty of the measurement. The results contained herein relate only to the item calibrated. This certificate shall not be reproduced except in full, without written approval of Control Company.

Nominal=Standard's Reading: As Left=Instrument's Reading: In Tol=In Tolerance; Min/Max=Acceptance Range; ±uc=Measurement Uncertainty; TUR=Test Uncertainty Ratio; Accuracy=±(Max-Min)/2; Date=MM/DD/YY

Wallace Resour

# Maintaining Accuracy:

In our opinion once calibrated your IR Therm with Wristband should maintain its accuracy. There is no exact way to determine how long calibration will be maintained. IR Therm with Wristbands change little, if any at all, but can be affected by aging, temperature, shock, and contamination.

# Recalibration:

For factory calibration and re-certification traceable to National Institute of Standards and Technology contact Control Company.

CONTROL COMPANY 4455 Rex Road Friendswood, TX 77546 USA Phone 281 482-1714 Fax 281 482-9448 service@control3.com www.control3.com

Control Company is an ISO 17025:2005 Calibration Laboratory Accredited by (A2LA) American Association for Laboratory Accreditation, Certificate No. 1750.01.

Control Company is ISO 9001:2000 Quality Certified by (DNV) Det Norske Veritas, Certificate No. CERT-01805-AQ-HOU.

International Laboratory Accreditation Cooperation (ILAC) - Multilateral Recognition Arrangement (MRA).