## **Job Hazard Analysis**

JHA Number 0035-PPD-EHS	Facility University of Vermont		Date Prepared 9/13/2019		Revision Date		
Approved by			Analysis by WALKER, CHRISTOPHER				
Description							
Bird Dropping Cleanup							
Smart Tabs							
Related Job Titles  * BUILDING TRADES SUPERVISOR  * BUILDING TRADESPERSON SENIOR  * FACILITIES REPAIRPERSON * FACILITIES TRADES SUPERVISOR * GROUNDS MAINTENANCE SPECIALIST	Related Departments  * DAVIS CENTER ZONE  * GROUNDS  * MEDICAL COMPLEX ZONE  * MEDPLEX PROJECT RENOVATIONS  * PROJECTS ZONE  * SOUTH ZONE  * TRAINING & COMPLIANCE  * TRINITY ZONE	Related I	ocations	Related MSDS	Training Requirements * OSHA 10 Hour Construction Card		

## **Additional Description**

Small scale cleaning of bird droppings

Common sense should be applied when executing any job. We do our best to implement hazard control measures such as engineering controls, administrative controls and personal protective equipment. When the hazard is still present the use of certain PPE may be required for one or more steps but not all of the steps. However, it may be prudent to don all required PPE for the duration of the JHA.

Step/ Area	Task Step Description	Hazards	Control Measure	PPE Required
1	Contact TCO to determine if an outside contractor is needed or if it can be conducted by the zone/crew Gather all equipment needed PPE Hoses cleaner squeegee etc	ergonomic cuts/scrapes	Follow the JHA Use proper PPE	Coveralls, Kleenguard (breathable); Safety glasses, UVM Issued; Boot, rubber; Face shield, plastic
2	Cleaninig:  Don all PPE Wash the material toward drains or to a collection point for containerizing and disposal at centennial field If washing to a collection point, use a shovel to gather the bulk material first and then wash down the area	Splashing Getting material in eyes/mouth slips/falls	use precautions when washing down. If on a roof, follow all roof rules and guidelins under the UVM Fall Protection Program If you are in a parking area or a spot with pedestrian/vehicle traffic, caution tape off your work area to keep people out. Use high visibility vest or similar clothing  Use of eye protection only with 1/2 face respirator. Face shield should also be used with this combination	Coveralls, Kleenguard (breathable); Face shield, plastic; Safety glasses, UVM Issued; Respirator cartridges, P100; Respirator, full-face; Boot, rubber

## JHA Number Facility Date Prepared Last Revision Date 0035-PPD-EHS University of Vermont 9/13/2019 Description Bird Dropping Cleanup Prepared By: Date: