

Type	JOB TASK	POTENTIAL RISK WHICH CAN BE CONTROLLED BY PPE	EYE	HAND	FOOT	BODY	OTHER REQUIREMENTS	RESP	HEAD	FALL PROTECTION	EAR	FACE	SPECIFIC PPE REQUIRED
Hotwork	Torch Cutting and Grinding	Flying/Piercing & Hot Objects, Sound Levels	ANSI Z87 Approved Safety Glasses	Leather Work Gloves	Ankle Supporting Shoe/Boot that meets ASTM F2413-17 M or F/I/75/C/75/PR	Cotton Coveralls				Fall Protection as needed. If working above 6' contact supervisor.	Hearing Protection either Plugs or Muffs	Faceshield	Follow UVM's Hot Work Permit Program for all spark generating activities.
Hotwork	Welding	Flying/Piercing & Hot Objects, Falling Objects	Welding Helmet	Welding Gloves	Ankle Supporting Shoe/Boot that meets ASTM F2413-17 M or F/I/75/C/75/PR	Apron and Arm Guards				Fall Protection as needed. If working above 6' contact supervisor.		Welding Helmet	Follow UVM's Hot Work Permit Program for all spark generating activities.
Hotwork	Braising - Large Tank	Flying Objects, Hot Objects, Falling Objects	ANSI Z87 Approved Safety Glasses	Leather Work Gloves	Ankle Supporting Shoe/Boot that meets ASTM F2413-17 M or F/I/75/C/75/PR	Cotton Coveralls				Fall Protection as needed. If working above 6' contact supervisor.			
Hotwork	Braising - Small Tank	Flying Objects, Hot Objects	ANSI Z87 Approved Safety Glasses	Leather Work Gloves	Ankle Supporting Shoe/Boot that meets ASTM F2413-17 M or F/I/75/C/75/PR	Cotton Coveralls				Fall Protection as needed. If working above 6' contact supervisor.			
Hotwork	Soldering	Flying Objects, Hot Objects	ANSI Z87 Approved Safety Glasses	Leather Work Gloves	Ankle Supporting Shoe/Boot that meets ASTM F2413-17 M or F/I/75/C/75/PR	Cotton Coveralls				Fall Protection as needed. If working above 6' contact supervisor.			
Hotwork	Copper Soldering / Roof Torching	Flying Objects, Hot Objects	ANSI Z87 Approved Safety Glasses	Leather Work Gloves	Ankle Supporting Shoe/Boot that meets ASTM F2413-17 M or F/I/75/C/75/PR	Cotton Coveralls				Fall Protection as needed. If working above 6' contact supervisor.			Follow UVM's Hot Work Permit Program for all spark generating activities.